

#### MJSSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY

BREATH ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPORT BEC-INNING- MAINT. CHECK

REPORT #6

| Complete this report at the time of the regular monthly preventive main Complete this report whenever the instrument is serviced or repaired at the original and send a servicible of the control of the  | and whonover it is also ad take a suite   |  |  |  |  |  |  |  |
|--|---|--|--|--|--|--|--|--|
| riedan the original and send a copy within 15 days to the Breath Alcoh   | of Program, DHSS.   |  |  |  |  |  |  |  |
| DATAMASTER SN / ZN # NAME OF AGENCY  | DATE OF INSPECTION  |  |  |  |  |  |  |  |
| 204087/127260 MSHP-IL LOCATION OF INSTRUMENT (STREET AND CITY)   | 07-06-2013<br>TIME OF INSPECTION  |  |  |  |  |  |  |  |
| LOCATION OF INSTRUMENT (STREET AND CITY)   | TIME OF INSPECTION  |  |  |  |  |  |  |  |
| MUS AT LEBANON ATRPORT (B.A.T.) VAN  | <u>)</u> 2133   |  |  |  |  |  |  |  |
| CHECKLIST: Place a mark in the box by each item if found to be satisfa where determined.) Unmarked items must be corrected before using ir   | ctory or if operating within established limits. (Write in observed values istrument. |  |  |  |  |  |  |  |
| DIAGNOSTIC CHECK (PRINTOUT ATTACHED)  DATE AND TIME (from printout) 07/66/13 21:33   |   |  |  |  |  |  |  |  |
|  | DETECTOR  |  |  |  |  |  |  |  |
|  | U FILTERS .   |  |  |  |  |  |  |  |
| ☐ HEATERS SAMPLE CHAMBER 50 °C ☐ QUARTZ STANDARD   |   |  |  |  |  |  |  |  |
| ☐ FLOW DETECTOR  | 1 CALIBRATION   |  |  |  |  |  |  |  |
| PUMP HIGH SPEED  | PRINTER   |  |  |  |  |  |  |  |
| ☐ INDICATOR LIGHTS   |   |  |  |  |  |  |  |  |
| SIMULATOR SOLUTION SUPPLIER REPCO MARKET ZN  | C [NOT# /2002 EXP. DATE 08-29-14  |  |  |  |  |  |  |  |
| SIMULATOR TEMP (34°C ± 0.2°C) 34, 1° C °C SIMU   | JLATOR SN <u>C-11098</u> EXP. DATE <u>09-27-13</u>                                    |  |  |  |  |  |  |  |
| CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USE  | D PER MAINTENANCE REPORT)   |  |  |  |  |  |  |  |
| Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)  |   |  |  |  |  |  |  |  |
| 0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE  0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE  0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE  |   |  |  |  |  |  |  |  |
| TEST 1 . 097 90 TEST 2 . 097   |   |  |  |  |  |  |  |  |
| PERFORM R.F.I. TEST (PRINTOUT ATTACHED)  |   |  |  |  |  |  |  |  |
| INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING I<br>(DO NOT INCLUDE SELF-ADMINISTERED TESTS)   | RANGES SINCE THE LAST MAINTENANCE REPORT:   |  |  |  |  |  |  |  |
| REFUSALS (004) (00509) (.0509)   | 014) Ø (.1519) Ø OVER .19 Ø   |  |  |  |  |  |  |  |
| LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO REUSE OTHER SIDE IF NECESSARY).  | STORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS          |  |  |  |  |  |  |  |
| · ·  |   |  |  |  |  |  |  |  |
| THUS ENSTRUMENT OPERATES WETHIN THE DEPT OF HEALTH & SENTAN SERVICES   |   |  |  |  |  |  |  |  |
| stecs.   |   |  |  |  |  |  |  |  |
|  |   |  |  |  |  |  |  |  |
| NSPECTING OFFICER  |   |  |  |  |  |  |  |  |
| SIGNATURE DY 10/1-0/1  | PRINT FULL NAME   |  |  |  |  |  |  |  |
| Shape Harden and Market and Marke | SC-7 STEVEN J. CHELDERS 563   |  |  |  |  |  |  |  |
| YPE II PERMIT NUMBER/EXPIRATION DATE   | TELEPHONE NUMBER  |  |  |  |  |  |  |  |
| 220413 / 12-27-2014 RETURN COMPLETED REPORT TO THE: Breath Alcohol Program MO F  | (573) 368-2345  |  |  |  |  |  |  |  |
| Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office 2875 James Blvd.  |   |  |  |  |  |  |  |  |

3101-188 STONYBROOK DRIVE RALEIGH, N.C. 27604 919-876-5480

### CERTIFICATE OF ANALYSIS

| MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. |
|--|
| LOT NUMBER: 12002                                |
| EXPIRATION DATE: August 29, 2014 at 11:59 p.m.   |

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 12002 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain \_\_\_\_\_\_ gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interferring substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is August 30, 2012

The expiration date for this lot number is August 29, 2014

at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marketing, Inc.

Form RM 02

# **BAC DataMaster** Evidence Ticket

BAC DATAMASTER SERIAL NUMBER 204087 MISSOURI STATE HIGHWAY PATROL 07/06/13

OFFICER I.D.: 063 MISCELLANEOUS DATA: EXPIRATION DATE: 12/27/14 PERMIT NORBER: MM8418 TESTING OFFICER: CHILDERS/S/J BEGINNING MAINT CHECK

# --- SUPERVISOR MODE ---

| BLANK TEST     | EXTERNAL STANDARD | BLANK TEST      | EXTERNAL STANDARD | BEADY TOUT     | EXTERNAL STANDARD | INTERNAL STANDARD | BLANK TEST    |
|----------------|-------------------|-----------------|-------------------|----------------|-------------------|-------------------|---------------|
| 60<br>60       | 768.              | <u>.</u><br>200 | 183               | ,<br>00<br>00  | .097              |                   | 000<br>0      |
| (N<br>(N<br>(N | 55.<br>17.        | <u>ក</u>        | 101 1 UA<br>4 UA  | 19<br>40<br>40 | E1:53             | M<br>M<br>M<br>M  | ស្ត<br>ស<br>ស |

<u>ا</u>

WIN.

E G

Ħ

. 897

Operator Signature

BEGUNTEN MARKET CHECK

Face This Side Down - This Edge In First

# **BAC DataMaster Evidence Ticket**

BAC DATAMASTER SERIAL NUMBER 204087 MISSOURI STATE HIGHWAY PATROL 07/06/13 P. ::33 ω

DIRENOUTIC CHECK ---

COMPUTER: OKAY

PROGRAM (84-87-2889): 

HEATERS

SAMPLE CHAMBER:

(J)

FLOW DETECTOR: 0X.AY

PUR

HIGH SPEED: OKAY

DETECTOR: 26.25

QUARTZ STANDARD: FILTERS:

7620

9KAY

CHLIBRATION:

282

pqrstuvwxyz(1)+-!"#\$%%'\>\*+,-./0123456789:;<=>?@ABCDEFG HIJKLMNOPQRSTUVWXYZ[\]^\_'abcdefghijklmno PRINTER TEST

Operator Signature SC-7

<del>(</del>98

BEC-ENNENE

MARNT CHECK

Face This Side Down - This Edge In First

# **BAC DataMaster Evidence Ticket**

BAC DATAMASTER SERIAL NUMBER 204087 MISSOURI STATE HIGHWAY PATROL 87/86/13

PERMIT NUMBER: 228413 EXPIRATION DATE: 12/27/14 MISCELLANEOUS DATA: OFFICER I.D.: SAME STATE/D.L.: MO/W1234567890 ARRESTING OFFICER: OFFICER I.D.: 560 SUBJECT NAME: ARREST TIME: 21:30 TESTING OFFICER: DOB: 07/06/13 BEGINNING MAINT, CHECK MATE OF CHILDERSVSVJ BEGINNING/MAINT/CK

BREATH AMALYSIS ---

INTERNAL STANDARD RADIO INTERFERENCE BLANK TEST

10 : 01

WERIFIED

1<u>0</u>1,001

Operator Signature\_

かかくしょう 24247

Note

## State of Missouri DEPARTMENT OF HEALTH



MO 580-0771 (7-88)

# PERMIT TYPE!



Lab. 4 (R7-88)

#### STEVEN J CHILDERS

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

###